

Cendence Release Notes

| | |
|-------------------|----------------------------------------------|
| Date: | 2018.11.16 |
| Firmware Version: | v02.00.0150 |
| DJI GO 4 app: | iOS v4.3.0 or above, Android v4.3.0 or above |

What's New?

- Fixed an issue when using a Cendence that did not have authorization to control the gimbal, where the customization of the Cendence LS and RS levers in the DJI GO 4 app did not work.
- Fixed an issue when an ordinary remote controller was set as the master controller in Dual Remote Controller Mode, where the customization of the Cendence LS and RS levers in the DJI GO 4 app did not work.
- Fixed a rare issue where there was an incorrect battery initialization fail prompt after the Cendence was powered on.

Notes:

- Ensure both the Master and Slave remote controllers are updated to the latest firmware to avoid control errors or camera and gimbal abnormalities.
- If the firmware update fails, restart the aircraft, remote controller, DJI GO 4 app, and then retry.



Cendence Release Notes

| | |
|-------------------|--------------|
| Date: | 2018. 07.18 |
| Firmware Version: | V 02.00.0120 |
| DJI GO 4 App: | V 4.2.20 |
| DJI Pilot Beta: | V 0.6.3 |

What's New?

- Added function that uses the LS and RS levels to adjust the maximum gimbal rotation speed for Cendence (Inspire 2 version 01.02.0200, and DJI GO 4 app version of 4.2.20 or above are required).
- Added function to customizable buttons. Added gimbal pitch auto return to center and turn downward 90° (Inspire 2 version 01.02.0200, and DJI GO 4 app version of 4.2.24* or above are required).

*Coming soon.

Cendence Release Notes

| | |
|-------------------|--------------|
| Date: | 2018. 04.18 |
| Firmware Version: | V 02.00.0090 |
| DJI GO 4 App: | V 4.2.8 |
| DJI Pilot Beta: | V 0.5.1 |

What's New?

- Added patch antenna detection. When connected, the Cendence LCD screen will always display "Patch antenna connected." When disconnected, the LCD will display "Patch antenna not detected" for a short time (approx. 10 seconds). Cendence will emit a sound at the moment of patch antenna connecting and disconnecting.
- Optimized the Focus Adjustment Knob (TD) control to fix an issue where focus adjustment range would be limited when used with some types of lens.
- Optimized control over adjusting the camera exposure parameters. Rotate the dial clockwise to increase the exposure and counter-clockwise to decrease it.
- Fixed an issue where the right dial would not set the camera parameters when using the Inspire 2 standard remote controller as the slave controller and Cendence as the master controller.
- Fixed an issue where the LCD would display "System error" when Cendence had a low battery level.
- If using the Inspire 2 standard remote controller as the slave controller, it must have firmware version v1.1.0010 or later.



Cendence Release Notes

| | |
|-------------------|--------------|
| Date: | 2017.11.09 |
| Firmware Version: | V 02.00.0030 |
| DJI GO 4 App: | V 4.1.15 |
| DJI Pilot Beta: | V 0.3.6 |

What's New?

- When disconnect from an aircraft, the LCD screen will now display whether the controller is set as a Master or Slave.
- Added firmware updating support for the Focus Handwheel and external GPS module when connected the Cendence remote controller.
- Optimized Focus Adjustment Knob (TD) control.