

OSMO Release Notes

2015.11.11

Firmware version updated to: V1.2.1.60

Major Updates

The Osmo firmware v1.1.1.50 released on the 6th November occasionally caused problems of system instability and abnormal filming behavior, and our team is working around the clock to resolve these issues.

Meanwhile, we are releasing firmware v1.2.1.60 for users to restore the Osmo to the factory default firmware. The firmware version 'v1.0.1.19+' should be displayed in the DJI GO app after the restoration is complete.

OSMO Release Notes

2015.11.06

Firmware version updated to: V1.1.1.50

Major Updates

1. When using the Key Combination to restore the Wi-Fi settings, the Wi-Fi frequency is also restored to 2.4 GHz.
2. Fixed issue of the camera restarting unexpectedly when recording video at 4096 x 2160 resolution.
3. Fixed issue of the pan axis drifting in timelapse mode during moving shots.