Ronin 2 Release Notes

Date :	2018.06.21
Firmware :	V 1.3.0.60
Ronin 2 App iOS :	V 1.1.0
Ronin 2 App Android :	V 1.1.0
DJI Pro Assistant for Ronin (PC) :	V 2.0.0
DJI Pro Assistant for Ronin (Mac):	V 2.0.0
User Manual :	V 1.2

What´s New?

• Added support for DJI Master Wheels and DJI Force Pro.

• Added support for switching between Profile and Follow mode and start/stop recording using Futaba controller.

• Fixed an issue where a downward-mounted gimbal would lose control when using the Track function.

• Fixed an occasional issue where the gimbal could not recenter itself when prompted.

• The gimbal will no longer restart when switching to the same system language.

• Fixed an issue where an incorrect prompt message would appear when powering off a gimbal set with an English system language.

• Fixed an issue where the Futaba R7008SB receiver could not control the gimbal.

• Reduced an issue where the pan axis would occasionally drift.

• Optimized gimbal performance when switching between Free and Follow modes.

• Fixed an issue where the gimbal would become stuck in Follow mode when using a remote controller.

Notes:

• Update the firmware through DJI Pro Assistant for Ronin by connecting the USB Type-C port on the Ronin 2 to your computer. Do not disconnect the gimbal from the computer during update process.

• Make sure to update both the Ronin 2 gimbal and remote controller to the latest firmware; otherwise, the remote controller will not be able to control the gimbal. Restart the gimbal and remote controller after the update is complete.

• Once the update starts, the motors will be power off. If updating firmware with a camera attached the Ronin 2, make sure to protect the camera from collisions.

• If the firmware update fails, restart the Ronin 2 and retry.

http://www.dji.com/ronin-2

Ronin 2 Release Notes

Date :	2017.10.26
Firmware :	V 1.2.0.50
Ronin 2 App iOS :	V 1.0.0
Ronin 2 App Android :	V 1.0.1
DJI Assistant 2 for PC :	V 1.1.6
DJI Assistant 2 for Mac:	V 1.1.6
User Manual :	V 1.0

What's New?

• Optimized gimbal performance when switching between Free mode and Follow mode.

• Fixed an occasional issue where batteries would suddenly power off.

• Reduced an issue where the roll axis would occasionally drift.

Notes:

• Update the firmware through DJI Assistant 2 by connecting the USB Type-C port on the Ronin 2 to your computer. Do not disconnect the gimbal from the computer during update process.

• Once the update starts, the motors will be power off. If updating firmware with a camera attached the Ronin 2, make sure to protect the camera from collisions.

• If the firmware update fails, restart the Ronin 2 and retry.