



## Matrice 200 Series Release Notes

---

Date:	2017.09.19
Aircraft Firmware:	V01.01.0303
Remote Controller Firmware:	V01.01.0001 V02.00.0020 (Cendence)
DJI GO 4 app:	iOS V 4.1.9, Android V 4.1.8
DJI Pilot APP :	Android V 0.3.6
CrystalSky Firmware:	V2.2.9.0

---

### What's New?

- Optimization of gimbal control experience.
- Fixed an issue where DJI AirSense abnormally reports an improper working status when powering on the aircraft.
- Fixed an issue where there is a delay running the current firmware version in both the DJI GO 4 or DJI Pilot apps.
- Fixed an issue where the gimbal abnormally swings when powering on the aircraft.
- Fixed an issue where the gimbal and aircraft yaw do not rotate at the same speed in Follow Mode when operated by one remote controller.

### Notes:

- The Zenmuse Z30 should be updated to v01.00.00.43 before using the gimbal with this firmware.
- Only newer Zenmuse XT models are compatible with the Matrice 200. A replacement may be required if your XT model isn't supported. Please contact DJI Support to learn more about various XT model compatibility. The Zenmuse XT gimbal adapter and DJI Pilot app are also required when used with the Matrice 200.
- If the firmware update fails, restart the aircraft and DJI GO 4, then try updating again.



## Matrice 200 Series Release Notes

---

Date:	2017.06.29
Aircraft Firmware:	V01.0.0100
Remote Controller Firmware:	V01.0.0210
DJI GO 4 app:	iOS V 4.1.3, Android V 4.1.3
DJI Pilot APP :	Android V 0.3.1

---

### What's New?

- Improved the display of flight control system parameters.
- Optimized vision system obstacle avoidance and positioning.

### Notes:

- The Zenmuse Z30 should be updated to v01.00.00.37 before using the gimbal with this firmware.
- Only newer Zenmuse XT models are compatible with the Matrice 200. A replacement may be required if your XT model isn't supported. Please contact DJI Support to learn more about various XT model compatibility. The Zenmuse XT gimbal adapter and DJI Pilot app are also required when used with the Matrice 200.
- If the firmware update fails, restart the aircraft and DJI GO 4, then try updating again.
- This firmware update is NOT for the remote controller. DO NOT update your remote controller and make sure your remote controller firmware stays at v01.0.0210.