

1

Osmo+ Release Notes

Date :	2017.01.22
Firmware :	v1.4.0.70
DJI GO App iOS :	v3.1.2
DJI GO App Android :	v3.1.2

What's New?

• Fixed issue where noise and vibrations occasionally appear in the gimbal.

- Calibrate the gimbal using auto-calibrate after upgrading firmware.
- If the firmware upgrade fails, restart Osmo+ and DJI GO app and retry.



Osmo+ Release Notes

Date :	2016.11.16
Firmware :	v1.3.0.50
DJI GO App iOS :	v3.1.0
DJI GO App Android :	v3.1.0

What's New?

• Added support for locking focus at infinite with one tap in the DJI GO app.

- Calibrate the gimbal using auto-calibrate after upgrading firmware.
- If the firmware upgrade fails, restart Osmo+ and DJI GO app and retry.



Osmo+ Release Notes

Date :	2016.10.20
Firmware :	v1.2.0.40
DJI GO App iOS :	v3.0.1
DJI GO App Android :	v3.0.0

What's New?

- Fixed occasional issue of audio and video streams being out of sync.
- Fixed occasional issue of video transmission being unexpectedly turned off.
- To increase stability and smoothness, camera will no longer attempt to focus when the gimbal moves while recording a video.

- Calibrate the gimbal using auto-calibrate after upgrading firmware.
- If the firmware upgrade fails, restart Osmo+ and DJI GO app and retry.



Osmo+ Release Notes

Date :	2016.09.13
Firmware :	v1.1.0.30
DJI GO App iOS :	v2.9.2
DJI GO App Android :	v2.9.1

What's New?

- Fixed issue of being unable to display the livefeed, occasionally occurring on first use of the Osmo+.
- Fixed a camera restart issue occurring during motion timelapse in some conditions.
- Fixed issue of gimbal being unable to re-center immediately after completing motion timelapse shooting.
- Fixed issue of gimbal being unable to re-center when reaching its maximum control angle.

- Latest version of DJI GO app (iOS V2.9.2 or Android V2.9.1) required if upgrade the firmware through DJI GO.
- After updating, auto calibrate the gimbal.
- If the firmware upgrade fails, restart Osmo+ and DJI GO app and retry.