

1

CrystalSky Release Notes

Date: 2017.09.20

Aircraft Firmware: V02.03.00.00

DJI GO 3 App : V 3.1.11

DJI GO 4 App : V 4.1.6

DJI Pilot Beta : V 0.3.6

What's New?

- Added separate updating for DJI GO and DJI GO 4 apps.
- Added support to DJI Spark.
- Optimized screen flash due to unexpected shutdown.
- Optimized both DJI GO and DJI GO 4 app editor interfaces and fixed some other issues.
- Optimized both DJI GO and DJI GO 4 app loading times.
- Optimized stability of both DJI GO and DJI GO 4 apps. Fixed an issue where system crashes.
- Fixed an issue where compass cannot work properly when the screen is rotated 180 degrees.
- Updated DJI GO app to 3.1.11.
- Updated DJI GO 4 app to 4.1.6.
- Updated DJI Pilot Beta to 0.3.6.



CrystalSky Release Notes

Date: 2017.08.17

Aircraft Firmware: V02.02.09.00

DJI GO 3 App : V 3.1.10

DJI GO 4 App : V 4.1.5

DJI Pilot Beta : V 0.3.4

What's New?

- Added availability of battery usage status on the battery page of Quick Settings.
- Optimized Quick Settings menu and some logos on the page.
- Optimized compass calibration program.
- Optimized Wi-Fi connection performance through Quick Settings.
- Updated battery profile.
- Fixed an issue where the system crashes when you press and hold down an image in the gallery.
- Fixed an issue where the monitor displays a green screen for the first few seconds of a local cache video.
- Optimized stability of both DJI GO and DJI GO 4 apps.
- Updated DJI GO app to 3.1.10.
- Updated DJI GO 4 app to 4.1.5.
- Updated DJI Pilot Beta to 0.3.4.



CrystalSky Release Notes

Date:	2017.08.04	
Aircraft Firmware:	V 02.02.08.01	
DJI GO 3 App:	V 3.1.8	
DJI GO 4 App:	V 4.1.3	
DJI Pilot Beta:	V 0.3.3	

What's New?

- Added a Flip Screen switch to the quick settings menu.
- Added Home Point setting as an F1/F2 button function.
- Fixed a rare video downlink error causing lag issues and blurring.
- Fixed lag issues and blurring when using the Osmo with a Wi-Fi connection.
- Fixed lag issues and blurring when using the Mavic with a Wi-Fi connection.
- Fixed lag issues and blurring that could occur after starting CrystalSky with HDMI devices connected.