

2015.09.29

Overview

DJI ESC Assistant software version updated to: v1.4

ESC firmware version updated to: v1.3

Major Updates

- The 2312E (800KV or 960KV) and 2212 motors are now supported by the DJI ESC Assistant.
- The E310's ESC (420S) firmware is now compatible with the 2312E (800KV or 960KV) and 2212 motors.

Notice

Be sure to update the DJI ESC Assistant software to the latest version before updating the E310 ESC firmware or configuring the 2312E (800KV or 960KV) or 2212 motors.