



DJI Power 1000 V2 Release Notes

Date:	2025.09.12
Firmware Version:	v01.00.10.00

What's New

- Fixed some known issues.

Notes:

If the update fails, follow the steps for troubleshooting.

1. Disconnect the computer and all connected devices from the power station.
2. Press and hold the power button for more than five seconds to power off the power station, and exit DJI Assistant 2 (Power Series).
3. Press and hold the AC button and the power button simultaneously. Connect the power station to the computer with a USB-C cable.
4. Retry updating the firmware to the latest version using DJI Assistant 2 (Power Series).



DJI Power 1000 V2 Release Notes

Date:	2025.09.04
Firmware Version:	v01.00.09.00

What's New

- Improved stability.
- Fixed some known issues.

Notes:

If the update fails, follow the steps for troubleshooting.

1. Disconnect the computer and all connected devices from the power station.
2. Press and hold the power button for more than five seconds to power off the power station, and exit DJI Assistant 2 (Power Series).
3. Press and hold the AC button and the power button simultaneously. Connect the power station to the computer with a USB-C cable.
4. Retry updating the firmware to the latest version using DJI Assistant 2 (Power Series).



DJI Power 1000 V2 Release Notes

Date:	2025.07.23
Firmware Version:	v01.00.08.00

What's New

- Improved stability.
- Fixed some known issues.

Notes:

If the update fails, follow the steps for troubleshooting.

1. Disconnect the computer and all connected devices from the power station.
2. Press and hold the power button for more than five seconds to power off the power station, and exit DJI Assistant 2 (Power Series).
3. Press and hold the AC button and the power button simultaneously. Connect the power station to the computer with a USB-C cable.
4. Retry updating the firmware to the latest version using DJI Assistant 2 (Power Series).