



DJI RS 3 Release Notes

Date:	2022.09.20
Firmware:	v01.00.01.00
DJI Ronin Image Transmitter (RavenEye) Firmware:	v01.03.00.30
DJI Ronin Tethered Control Handle Firmware:	v32.33
DJI Ronin App iOS:	v1.5.0
DJI Ronin App Android:	v1.5.2
User Manual:	v1.2

What 's New?

- Added support for BG30 Grip.
- Optimized the follow curves for PTF mode to make the follow speed of tilt and pan axes stay the same.
- Disabled the control stick for the roll and pan axes in FPV mode.

Notes:

- Motor parameters are reset after updating firmware. Make sure to autotune DJI RS 3.
- Make sure that the DJI Ronin app is the latest version when updating the firmware.
- Update the firmware using the DJI Ronin app by connecting the DJI RS 3 via Bluetooth. Do not disconnect the DJI Ronin app and DJI RS 3 during the update process.
- Update the firmware for the DJI Ronin Image Transmitter using the DJI Ronin app by connecting the Image Transmitter via Wi-Fi. Do not disconnect the DJI Ronin app and DJI Ronin Image Transmitter during the update process.
- If DJI RS 3 has a camera attached and is powered on while updating the firmware, make sure to protect the camera and lens as the motors will power off during the update.
- If the firmware update fails, restart DJI RS 3 and retry.



DJI RS 3 Release Notes

Date:	2022.06.29
Firmware:	v01.00.00.00
DJI Ronin Image Transmitter (RavenEye) Firmware:	v01.03.00.30
DJI Ronin Tethered Control Handle Firmware:	v32.33
DJI Ronin App iOS:	v1.5.0
DJI Ronin App Android:	v1.5.0
User Manual:	v1.2

What 's New?

- Added Recenter and Lock option for the automated axis locks when the gimbal is powered on/off.
- Added ability to access Timelapse, Track and Panorama by sliding left on the touchscreen.
- Added focus control through the Ronin app with the DJI RS focus motor attached.
- Added auto power off when the gimbal is in sleep mode and idle for more than 10 minutes. The feature is available when sleep mode is entered by pressing the power button.

Notes:

- Motor parameters are reset after updating firmware. Make sure to autotune DJI RS 3.
- Make sure that the DJI Ronin app is the latest version when updating the firmware.
- Update the firmware using the DJI Ronin app by connecting the DJI RS 3 via Bluetooth. Do not disconnect the DJI Ronin app and DJI RS 3 during the update process.
- Update the firmware for the DJI Ronin Image Transmitter using the DJI Ronin app by connecting the Image Transmitter via Wi-Fi. Do not disconnect the DJI Ronin app and DJI Ronin Image Transmitter during the update process.
- If DJI RS 3 has a camera attached and is powered on while updating the firmware, make sure to protect the camera and lens as the motors will power off during the update.
- If the firmware update fails, restart DJI RS 3 and retry.