



## Mavic 2 Pro/Zoom Release Notes

---

Date :	2018.10.11
Aircraft Firmware :	v01.00.01.00
DJI GO 4 App iOS :	v4.3.3
DJI GO 4 App Android :	v4.3.2

---

### What 's New?

- Added ability to make a selection and adjust the flight speed and duration for Hyperlapse (requires DJI GO 4 v4.3.2 or higher).
- Added ability to delete Hyperlapse and Panorama RAW footage in Playback (requires DJI GO 4 v4.3.2 or higher).
- Added ability to enable and disable Vision Systems by using remote controller's C1 and C2 buttons (requires DJI GO 4 v4.3.2 or higher).
- Enabled Lateral Vision Systems for QuickShots sub-modes of Circle, Helix, and Boomerang. Refer to the Mavic 2 User Manual for more details about the requirements for obstacle sensing.
- Optimized ActiveTrack 2.0.
- Improved photo quality for Panorama.
- Improved aircraft flight stability.

### Notes:

- Restart the aircraft and remote controller after upgrade is complete.
- Please note that firmware update may reset various Main Controller Settings, such as the RTH Altitude and Maximum Flight Distance, to factory defaults. Before the update, take note of your preferred DJI GO 4 settings, and readjust them after the update to suit your preference.
- If the firmware upgrade fails, restart aircraft, remote controller and DJI GO 4 or DJI Assistant 2 for Mavic, and retry.



## Mavic 2 Pro/Zoom Release Notes

---

Date :	2018.08.23
Aircraft Firmware :	v01.00.00.00
DJI GO 4 App iOS :	v4.3.0
DJI GO 4 App Android :	v4.3.0

---

### What 's New?

- Added Hyperlapse mode, including four sub-modes: Free, Circle, Course Lock, and Waypoints.
- Added Dolly Zoom sub-mode for QuickShots (Mavic 2 Zoom only).
- Added Enhanced HDR and HyperLight shooting modes.
- Added Super Resolution sub-mode for Panorama (Mavic 2 Zoom only).
- Added 2x digital zoom (Mavic 2 Zoom only. Available when recording video in 1080p 24/25/30 fps).
- Added Emergency RTH and Emergency Landing for Low Battery RTH.
- Adjusted the low battery warning level to 25%.
- Improved stability for POI by optimizing the way the location of the subject is measured (Mavic 2 Zoom only).
- Fixed the occasional issue in Panorama where the camera was unable to take a photo and improved the overall photo quality in Panorama.
- Fixed the issue where the aircraft would move unexpectedly due to compass interference.
- Fixed the occasional issue where the gimbal would not recenter after exiting QuickShots.
- Fixed the AE flicker issue (Mavic 2 Pro only) and green point issue (Mavic 2 Zoom only). Improved the overall photo quality of both Mavic 2 Pro/Zoom.
- Optimized the performance of the Vision Systems.
- Added 2 m minimum flight altitude to ActiveTrack 2.0.
- Fixed the occasional issue in QuickShots where the camera was unable to record a video and improved the overall video quality in QuickShots.

### Notes:

- Please note that there is no minimum flight altitude when the speed is fixed in the Free sub-mode of Hyperlapse. Be sure to fly with caution.