



Zenmuse XT2 Release Notes

Date:	2020.05.08
Firmware:	v01.00.00.30
Camera 1 Firmware:	v01.00.00.34
Camera 2 Firmware:	v06.02.20.00
Gimbal Firmware:	v00.02.06.04
DJI Pilot App Android:	v1.7.2 or later

What 's New?

- Added support for Matrice 300 RTK.
- Optimized gimbal performance when controlling two gimbals together with Matrice 210 and Matrice 210 RTK.

Notes:

- This update is for the Zenmuse XT2 gimbal and camera only. It cannot be used to update the aircraft or the Intelligent Flight Battery.
- The Zenmuse XT2 must be connected to the aircraft before starting this update.
- Ensure that there are no other updates on the microSD card and that the battery level is above 50%.
- DO NOT power off the aircraft when updating. It takes approximately five minutes to update the firmware. The aircraft beeps when the update is complete.



Zenmuse XT2 Release Notes

Date:	2019.02.27
Firmware:	v01.00.00.20
Camera 1 Firmware:	v01.00.00.34
Camera 2 Firmware:	v06.02.20.00
Gimbal Firmware:	v00.02.06.04
DJI Pilot App Android:	v1.2

What 's New?

- Compatible with Matrice 200 Series V2 aircrafts.

Notes:

- This update is for the Zenmuse XT2 gimbal and camera only. It cannot be used to update the aircraft or the Intelligent Flight Battery.
- The Zenmuse XT2 must be connected to the aircraft before starting this update.
- Ensure that there are no other updates on the microSD card and that the battery level is above 50%.
- It takes approximately five minutes to update the firmware. The aircraft beeps when the update is complete.



Zenmuse XT2 Release Notes

Date:	2018.08.23
Firmware:	v01.00.00.06
DJI Pilot App Android:	v0.6.3

What's New?

- Optimized the R-JPEG photo quality for when taking photos with many subjects.
- Fixed an issue where GPS information displayed in a photo's Exif is incorrect.
- Fixed an issue which occurred when resetting the camera parameters where the preview of the infrared camera is distorted.
- Fixed an issue which occurred when the camera parameters reset where a prompt incorrectly appears stating that the SD card was not inserted.
- Fixed an issue where the video duration displayed in the app is incorrect.
- Fixed an issue where the infrared camera stops after taking a photo in Interval mode.

Notes:

- This update is for the Zenmuse XT2 gimbal and camera only. It cannot be used to update the aircraft or the Intelligent Flight Battery.
- The Zenmuse XT2 must be connected to the aircraft before starting this update.
- Ensure that there are no other updates on the microSD card and that the battery level is above 50%.
- It takes approximately five minutes to update the firmware. The aircraft beeps when the update is complete.