

Date: 2023.01.13

Aircraft Firmware: v06.00.06.00

Remote Controller Firmware: v01.02.03.54

DJI Pilot 2 App Android: v6.0.1.6

D-RTK 2 Mobile Station: v03.01.0000 (incl. Matrice version)

Intelligent Battery Station: v04.03.03.00*
Intelligent Flight Battery: v02.00.20.46

DJI Assistant 2 (Enterprise Series): v2.1.7

Aircraft / Remote Controller: DJI Assistant 2 / App

D-RTK 2 Mobile Station: DJI Assistant 2

The built-in DJI Pilot 2 app: will be updated with the Remote

Firmware Upgrade Method: Controller firmware

Intelligent Battery Station: App (Connect the Battery Station to the

remote controller and update it on the HMS page in the DJI Pilot $2\,$

app.)

What's new?

Matrice 30 Series Dock Version

- Optimized estimated battery power level.
- Optimized the broken propeller detection logic for Matrice 30 Series Dock Version. *
- Added support for Matrice 30 Series Dock Version to operate with DJI Dock.
- ullet Added function for Matrice 30 Series Dock Version to support deployment site selection using DJI Pilot 2 app. *
- Optimized the takeoff-condition logics of Matrice 30 Series Dock Version. *

^{*} The Intelligent Battery Station firmware update includes the battery update. After being updated, the battery station version will be shown as v05.02.12.31 in DJI Pilot 2.

^{*} This feature is required to use with DJI Dock (firmware version v01.01.03.00) and DJI RC Plus remote controller (firmware version v01.02.03.54).



DJI Matrice 30 Series Release Notes DJI RC Plus

- Added function for DJI Dock deployment and operations. *
- Added function for deployment site selection with Matrice 30 Series aircraft before dock deployment.
- * This feature is required to use with DJI Dock (firmware version v01.01.03.00) and Matrice 30 Series Dock Version (firmware version v06.00.06.00).

Notes:

• Due to the characteristics of the infrared sensor, it is possible that the sensor will burn before burn protection is triggered. To avoid the sensor from burning, DO NOT operate the camera in direct sunlight. For minor burns, let the aircraft sit or manually perform FFC to try and restore the sensor.

- Visit https://www.dji.com/matrice-30/downloads to download manuals such as the Quick Start Guide, Safety Guidelines and User Manual.
- Visit https://www.dji.com/matrice-30/video to watch the tutorial videos.
- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.
- Scan the QR code to contact DJI Support:





Date: 2022.12.02

Aircraft Firmware: v05.01.00.00

Remote Controller Firmware: v01.02.03.42

DJI Pilot 2 App Android: V5.1.1.8

D-RTK 2 Mobile Station: v03.01.0000 (incl. Matrice version)

Intelligent Battery Station: v04.03.01.47*
Intelligent Flight Battery: v02.00.20.41

DJI Assistant 2 (Enterprise Series): v2.1.6

Aircraft / Remote Controller: DJI Assistant 2 / App

D-RTK 2 Mobile Station: DJI Assistant 2

The built-in DJI Pilot 2 app: will be updated with the Remote

Firmware Upgrade Method: Controller firmware

Intelligent Battery Station: App (Connect the Battery Station to the

remote controller and update it on the HMS page in the DJI Pilot $2\,$

app.)

What's new?

• Fixed issue where importing KMZ file fails.

Notes:

- Visit https://www.dji.com/matrice-30/downloads to download manuals such as the Quick Start Guide, Safety Guidelines and User Manual.
- Visit https://www.dji.com/matrice-30/video to watch the tutorial videos.
- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.
- Scan the QR code to contact DJI Support:

^{*} The Intelligent Battery Station firmware update includes the battery update. After being updated, the battery station version will be shown as v05.02.12.31 in DJI Pilot 2.

^{*} Due to the characteristics of the infrared sensor, it is possible that the sensor will burn before burn protection is triggered. To avoid the sensor from burning, DO NOT operate the camera in direct sunlight. For minor burns, let the aircraft sit or manually perform FFC to try and restore the sensor.







Date: 2022.11.08

Aircraft Firmware: v05.01.00.00

Remote Controller Firmware: v01.02.03.38

DJI Pilot 2 App Android: V5.1.1.4

D-RTK 2 Mobile Station: v03.01.0000 (incl. Matrice version)

Intelligent Battery Station: v04.03.01.47*
Intelligent Flight Battery: v02.00.20.41

DJI Assistant 2 (Enterprise Series): v2.1.3

Aircraft / Remote Controller: DJI Assistant 2 / App

D-RTK 2 Mobile Station: DJI Assistant 2

The built-in DJI Pilot 2 app: will be updated with the Remote

Firmware Upgrade Method: Controller firmware

Intelligent Battery Station: App (Connect the Battery Station to the

remote controller and update it on the HMS page in the DJI Pilot 2

app.)

What's new?

- Added support for DJI Pilot 2 to download online geoid files.
- Added support for importing and exporting MapTiler offline maps.
- Added support for DJI Pilot 2 message notifications.
- Added support for Al Spot to use metering.
- Optimized estimated battery power level.
- Optimized estimated Waypoint task operation time.
- Optimized effectiveness of sun burn protection for the infrared camera sensor.

Notes:

- Visit https://www.dji.com/matrice-30/downloads to download manuals such as the Quick Start Guide, Safety Guidelines and User Manual.
- Visit https://www.dji.com/matrice-30/video to watch the tutorial videos.

^{*} The Intelligent Battery Station firmware update includes the battery update. After being updated, the battery station version will be shown as v05.02.12.31 in DJI Pilot 2.

^{*} Due to the characteristics of the infrared sensor, it is possible that the sensor will burn before burn protection is triggered. To avoid the sensor from burning, DO NOT operate the camera in direct sunlight. For minor burns, let the aircraft sit or manually perform FFC to try and restore the sensor.



- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.
- Scan the QR code to contact DJI Support:





Date: 2022.09.14

Aircraft Firmware: v04.03.00.00

Remote Controller Firmware: v01.02.02.50

DJI Pilot 2 App Android: v4.2.1.0

D-RTK 2 Mobile Station: v03.01.0000 (incl. Matrice version)

Intelligent Battery Station: v04.02.01.03*
Intelligent Flight Battery: v02.00.20.37

DJI Assistant 2 (Enterprise Series): v2.1.3

Aircraft / Remote Controller: DJI Assistant 2 / App

D-RTK 2 Mobile Station: DJI Assistant 2

The built-in DJI Pilot 2 app: will be updated with the Remote

Firmware Upgrade Method: Controller firmware

Intelligent Battery Station: App (Connect the Battery Station to the

remote controller and update it on the HMS page in the DJI Pilot 2

app.)

What's new?

- Added sun burn protection for the infrared camera sensor. When the camera detects the sun, it will automatically close the infrared shutter to protect the infrared camera. * This function is enabled by default and can be disabled or enabled in the app.
- Improved barometer stability.

Notes:

- Visit https://www.dji.com/matrice-30/downloads to download manuals such as the Quick Start Guide, Safety Guidelines and User Manual.
- Visit https://www.dji.com/matrice-30/video to watch the tutorial videos.
- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.

^{*} The Intelligent Battery Station firmware update includes the battery update. After being updated, the battery station version will be shown as v05.02.12.31 in DJI Pilot 2.

^{*} Due to the characteristics of the infrared sensor, it is possible that the sensor will burn before burn protection is triggered. To avoid the sensor from burning, DO NOT operate the camera in direct sunlight. For minor burns, let the aircraft sit or manually perform FFC to try and restore the sensor.



• Scan the QR code to contact DJI Support:





Date: 2022.08.18

Aircraft Firmware: v04.02.00.00

Remote Controller Firmware: v01.02.02.40

DJI Pilot 2 App Android: v4.1.1.12

D-RTK 2 Mobile Station: v03.01.0000 (incl. Matrice version)

Intelligent Battery Station: v04.02.01.03*
Intelligent Flight Battery: v02.00.20.37

DJI Assistant 2 (Enterprise Series): v2.1.3

Aircraft / Remote Controller: DJI Assistant 2 / App

D-RTK 2 Mobile Station: DJI Assistant 2

The built-in DJI Pilot 2 app: will be updated with the Remote

Firmware Upgrade Method: Controller firmware

Intelligent Battery Station: App (Connect the Battery Station to the remote controller and update it on the HMS page in the DJI Pilot 2

app.)

What's new?

• Fixed issue where app crashes when displaying ADS-B information on map.

Notes:

- Visit https://www.dji.com/matrice-30/downloads to download manuals such as the Quick Start Guide, Safety Guidelines and User Manual.
- Visit https://www.dji.com/matrice-30/video to watch the tutorial videos.
- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.
- Scan the QR code to contact DJI Support:



^{*} The Intelligent Battery Station firmware update includes the battery update. After being updated, the battery station version will be shown as v05.02.12.31 in DJI Pilot 2.



Date: 2022.07.21

Aircraft Firmware: v04.02.00.00

Remote Controller Firmware: v01.02.02.38

DJI Pilot 2 App Android: v4.1.1.9

D-RTK 2 Mobile Station: v03.01.0000 (incl. Matrice version)

Intelligent Battery Station: v04.02.01.03*
Intelligent Flight Battery: v02.00.20.37

DJI Assistant 2 (Enterprise Series): v2.1.3

Aircraft / Remote Controller: DJI Assistant 2 / App

D-RTK 2 Mobile Station: DJI Assistant 2

The built-in DJI Pilot 2 app: will be updated with the Remote

Firmware Upgrade Method: Controller firmware

Intelligent Battery Station: App (Connect the Battery Station to the remote controller and update it on the HMS page in the DJI

Pilot 2 app.)

What's new?

- Optimized imported third-party KMZ files.
- Fixed an issue where uploading and downloading flight route files from DJI FlightHub 2 failed.

Notes:

- Visit https://www.dji.com/matrice-30/downloads to download manuals such as the Quick Start Guide, Safety Guidelines and User Manual.
- Visit https://www.dji.com/matrice-30/video to watch the tutorial videos.
- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.
- Scan the QR code to contact DJI Support:



^{*} The Intelligent Battery Station firmware update includes the battery update. After being updated, the battery station version will be shown as v05.02.12.31 in DJI Pilot 2.



Date: 2022.07.14

Aircraft Firmware: v04.02.00.00

Remote Controller Firmware: v01.02.02.30

DJI Pilot 2 App Android: v4.1.1.3

D-RTK 2 Mobile Station: v03.01.0000 (incl. Matrice version)

Intelligent Battery Station: v04.02.01.03*
Intelligent Flight Battery: v02.00.20.37

DJI Assistant 2 (Enterprise Series): v2.1.3

Aircraft / Remote Controller: DJI Assistant 2 / App

D-RTK 2 Mobile Station: DJI Assistant 2

The built-in DJI Pilot 2 app: will be updated with the Remote

Firmware Upgrade Method: Controller firmware

Intelligent Battery Station: App (Connect the Battery Station to the remote controller and update it on the HMS page in the DJI

Pilot 2 app.)

What's new?

- Al Spot-Check is now available for Matrice 30 series.
- Added real-time voice broadcasting for M30 series when using with the speaker, improving broadcasting efficiency together with text-to-speech.
- Updated Mapbox to MapTiler. A maximum area of 50 square kilometers of offline map can be downloaded at one time.
- Added support for saving Maintain Positioning Accuracy setting after the aircraft is powered off.
- Added support to display the high battery power storage time of the TB30 battery.
- Optimized anomaly detecting, switching, and alarm logic of the IMU.
- Optimized hovering accuracy in Waypoint missions.
- Optimized modeling accuracy in Mapping missions and Oblique missions.
- Optimized power diagnostic logic for the TB30 battery to reduce false alarm battery power.
- Fixed an issue where the ESC prompted a false alarm indicating overheating in the motor.

^{*} The Intelligent Battery Station firmware update includes the battery update. After being updated, the battery station version will be shown as v05.02.12.31 in DJI Pilot 2.



- Fixed an issue where the flight parameters were reset after updating the firmware.
- Fixed an issue where the battery station may occasionally stop charging other TB30 batteries after inserting two fully charged TB30 batteries.
- Fixed an occasional issue where the battery station may stop charging the WB37 batteries for a short time.

Notes:

- Visit https://www.dji.com/matrice-30/downloads to download manuals such as the Quick Start Guide, Safety Guidelines and User Manual.
- Visit https://www.dji.com/matrice-30/video to watch the tutorial videos.
- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.
- Scan the QR code to contact DJI Support:





Date: 2022.06.20

Aircraft Firmware: v04.01.00.20

Remote Controller Firmware: v01.02.01.34

DJI Pilot 2 App Android: v4.0.1.21

D-RTK 2 Mobile Station: v03.01.0000 (incl. Matrice version)

Intelligent Battery Station: v04.01.00.00*
Intelligent Flight Battery: v02.00.20.34

DJI Assistant 2 (Enterprise Series): v2.1.3

Aircraft / Remote Controller: DJI Assistant 2 / App

D-RTK 2 Mobile Station: DJI Assistant 2

The built-in DJI Pilot 2 app: will be updated with the Remote

Firmware Upgrade Method: Controller firmware

Intelligent Battery Station: App (Connect the Battery Station to

the remote controller and update it on the HMS page in the DJI

Pilot 2 app.)

What's new?

• Added support for Remote ID in Japan.

Notes:

- Visit https://www.dji.com/matrice-30/downloads to download manuals such as the Quick Start Guide, Safety Guidelines and User Manual.
- Visit https://www.dji.com/matrice-30/video to watch the tutorial videos.
- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.
- Scan the QR code to contact DJI Support:



^{*} The Intelligent Battery Station firmware update includes the battery update. After being updated, the battery station version will be shown as v05.02.12.29 in DJI Pilot 2.



Date: 2022.06.07

Aircraft Firmware: v04.01.00.10

Remote Controller Firmware: v01.02.01.30

DJI Pilot 2 App Android: v4.0.1.17

D-RTK 2 Mobile Station: v03.01.0000 (incl. Matrice version)

Intelligent Battery Station: v04.01.00.00*
Intelligent Flight Battery: v02.00.20.34

DJI Assistant 2 (Enterprise Series): v2.1.3

Aircraft / Remote Controller: DJI Assistant 2 / App

D-RTK 2 Mobile Station: DJI Assistant 2

The built-in DJI Pilot 2 app: will be updated with the Remote

Firmware Upgrade Method: Controller firmware

Intelligent Battery Station: App (Connect the Battery Station to

the remote controller and update it on the HMS page in the DJI

Pilot 2 app.)

What's new?

- Optimized imported KML files. After importing KML files when using Waypoint mission, users can select
 the flight route altitude from Relative to Takeoff Point (ALT), Ellipsoidal Height (WGS84), and ASL
 (EGM96).
- Optimized and improved system stability.

Notes:

- Visit https://www.dji.com/matrice-30/downloads to download manuals such as the Quick Start Guide, Safety Guidelines and User Manual.
- Visit https://www.dji.com/matrice-30/video to watch the tutorial videos.
- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.
- Scan the QR code to contact DJI Support:

^{*} The Intelligent Battery Station firmware update includes the battery update. After being updated, the battery station version will be shown as v05.02.12.29 in DJI Pilot 2.







Date: 2022.04.29

Aircraft Firmware: v04.01.00.00

Remote Controller Firmware: v01.02.01.24

DJI Pilot 2 App Android: v4.0.1.13

D-RTK 2 Mobile Station: v03.01.0000 (incl. Matrice version)

Intelligent Battery Station: v04.01.00.00*
Intelligent Flight Battery: v02.00.20.34

DJI Assistant 2 (Enterprise Series): v2.1.3

Aircraft / Remote Controller: DJI Assistant 2 / App

D-RTK 2 Mobile Station: DJI Assistant 2

The built-in DJI Pilot 2 app: will be updated with the Remote

Firmware Upgrade Method: Controller firmware

Intelligent Battery Station: App (Connect the Battery Station to the remote controller and update it on the HMS page in the DJI

Pilot 2 app.)

- Visit https://www.dji.com/matrice-30/downloads to download manuals such as the Quick Start Guide, Safety Guidelines and User Manual.
- Visit https://www.dji.com/matrice-30/video to watch the tutorial videos.
- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.
- Scan the QR code to contact DJI Support:



^{*} The Intelligent Battery Station firmware update includes the battery update. After being updated, the battery station version will be shown as v05.02.12.29 in DJI Pilot 2.