

Osmo Mobile Release Notes

Date :	2016.10.19
Firmware :	v1.2.0.40
DJI GO App iOS :	v3.0.1
DJI GO App Android :	v3.0.0

What's New?

- Added option for gimbal speed control with the joystick.
- Added option for enabling or disabling detection when mobile phone is mounted to the gimbal.
- Added abnormal status update. By holding the trigger and pressing the shutter button three times, the Osmo Mobile will flash to indicate a specific problem.
- Switching to Flashlight mode is smoother now.
- Fixed issue of gimbal shaking unexpectedly after shooting long exposures or timelapses.
- Fixed issue of Osmo Mobile shaking abnormally when the gimbal's balance is not adjusted properly.

Notes:

• If the firmware upgrade fails, restart Osmo Mobile and DJI GO, and retry.