

Release Date: 2025.11.04

Zenmuse H30 Series Firmware: v10.05.02.01

Firmware Upgrade Method: microSD card

Compatible Firmware and Software Required: M400 Aircraft: v16.00.00.05

DJI RC Plus 2 Remote Controller: v01.64.07.02

DJI Pilot 2 App: v16.0.0.49

M350 RTK Aircraft: v14.01.00.17 M300 RTK Aircraft: v64.01.00.09

DJI RC Plus Remote Controller: v06.02.13.11

DJI Pilot 2 App: v14.3.0.35

### What's Fixed

- With the Matrice 400 aircraft, Al Subject Recognition is supported when using the wide-angle camera.
- Optimized the Photo Transfer function in FlightHub 2.
- Fixed an occasional issue in FlightHub 2 where backend download would freeze.

#### Notes:

• Make sure that the aircraft firmware, the remote controller firmware, the H30 series firmware, and the DJI Pilot 2 App are all updated to the latest version.



Release Date: 2025.06.10 Zenmuse H30 Series Firmware: v10.04.04.03

Firmware Upgrade Method: microSD card

Compatible Firmware and Software Required: M350 RTK Aircraft: v14.01.00.06

M300 RTK Aircraft: v64.01.00.04

DJI RC Plus Remote Controller: v05.02.13.04

DJI Pilot 2 App: v13.0.4.1

## **What's Fixed**

• Added support for Matrice 400. The following functions are supported when used together:

- 1) Supports Subject Zoom function on DJI FlightHub.
- 2) Supports Al Subject Recognition function.
- 3) Supports Power Line Inspection function.

### Notes:

• Make sure that the aircraft firmware, the remote controller firmware, the H30 series firmware, and the DJI Pilot 2 App are all updated to the latest version.



Release Date: 2024.11.07

Zenmuse H30 Series Firmware: v10.02.0804

Firmware Upgrade Method: microSD card / Update All in App Compatible Firmware and Software Required: M350 RTK Aircraft: v10.01. 0805

M300 RTK Aircraft: v60.01.0806

DJI RC Plus Remote Controller: v05.02.1301

DJI Pilot 2 App: v10.1.8.16

#### What's Fixed

- Added support to adjust the night scene mode of the zoom camera in SBS view.
- Optimized zoom adjustment of the infrared thermal camera.
- Added IR Temperature Calibration. Please operate under professional guidance.

### Notes:

• Make sure that the aircraft firmware, the remote controller firmware, the H30 series firmware, and the DJI Pilot 2 App are all updated to the latest version.



Release Date: 2024.07.18

Zenmuse H30 Series Firmware: v10.01.0703

Firmware Upgrade Method: microSD card / Update All in App Compatible Firmware and Software Required: M350 RTK Aircraft: v10.01. 0009

M300 RTK Aircraft: v60.01.0003

DJI RC Plus Remote Controller: v05.02.1106

DJI Pilot 2 App: v10.1.0.30

#### What's Fixed

- Added support for switching the night scene level automatically according to the ambient brightness if Auto Night Scene mode is enabled and saving Auto Night Scene setting after powering off.
- Fixed issue: When Pre-Rec mode was enabled, the night scene level cannot be automatically enabled if Night Scene mode was set to Auto.
- Optimized the alignment between photos taken by the zoom camera and the selected area in High-Res Photo mode in some scenarios.
- Optimized the image quality of visible-light cameras in some scenarios.
- Optimized the logic of video splitting. The maximum splitting length of the video is up to 45 minutes.
- Optimized Panorama mode to reduce shooting time.
- Fixed issue: When restarting the H30 series payload with Pre-Rec mode enabled, the recorded video file displayed a different shooting time from the actual time by 8 hours.
- Fixed issue: If the zoom ratio was set to more than 200x for the waypoint action, the zoom camera cannot reach the preset zoom ratio during the flight task.
- Added support to detect the storage fragmentation of the microSD card. A prompt will be displayed to remind users to back up files and format if it is severely fragmented.

#### Notes:

• Make sure that the aircraft firmware, the remote controller firmware, the H30 series firmware, and the DJI Pilot 2 App are all updated to the latest version.

https://enterprise.dji.com/zenmuse-h30-series